Errata

The following corrections are made in "Autonomous Formation Flyer (AFF) Sensor Technology Development" by G. Purcell, D. Kuang, S. Lichten, S.-C. Wu, and L. Young, which appeared in *The Telecommunications and Mission Operations Progress Report 42-134, April–June 1998*, August 15, 1998:

On page 5, in the computations in the last paragraph of Section II.A, the value of σ_R should be 3.35×10^{-3} m, and the value of σ_{ϕ} should be 2.5×10^{-6} m.

On page 19, in the discussion following Eq. (20), the value of A is reasonable, but the argument involving the antenna patterns is spurious and should be deleted.

The authors thank Jeff Tien for pointing out these errors.